

PROW Problem Reports				10/06/2022 12:06			
S1	S1	30	34	S1	S1	31	
NYMNPAs total	36	21	<Job No required				
NYCC total	12	0	<Job No required				
Emailed Date	To	Reply Ref	Reply Date	Description	Grid Ref/PROW Number	Lapsed time	Notes
28/03/2022	NYCC	71672	29/03/2022	Stile top tread (roadside) to high	NZ50304-09356	75	
30/06/2021	NYCC	70419	05/07/2021	Stile top tread to top rail too big	NZ52785-05201	346	
30/06/2021	NYCC	71666	05/07/2021	Stile top tread to top rail too big	NZ52945-05342	346	
30/06/2021	NYCC	71667	05/07/2021	Stile top tread to top rail too big	NZ52953-05347	346	
30/06/2021	NYCC	67327	05/07/2021	Stile top tread to top rail too big	NZ54473-06501	346	
22/11/2021	NYCC	71137	29/11/2021	Stile out of repair	NZ769-112	201	High Whims to Old Castle Farm, Tranmire
22/11/2021	NYCC	71138	29/11/2021	Barbed wire fence	NZ769-116	201	High Whims to Old Castle Farm, Tranmire
22/11/2021	NYCC	71139	29/11/2021	Woodland	NZ769-117	201	High Whims to Old Castle Farm, Tranmire
22/03/2022	NYCC	71138	23/03/2022	Post /wire fence obstruction - gate required	NZ76946-11713	81	Tranmire Grange
22/03/2022	NYCC	71651	23/03/2022	Post /wire fence obstruction - gate required	NZ76976-11749	81	Tranmire Grange
25/05/2022	NYCC	71945	26/05/2022	Barbed wire at stile and high step	SE467-915	17	Kepwick
25/05/2022	NYCC	66914	26/05/2022	Bridge decking missing	SE468-913	17	Kepwick
13/08/2020	NYMNPAs	4000	22/04/2022	Stile step needs repairing	NZ55941-01344	667	
30/09/2020	NYMNPAs		05/07/2021	footpath between SE54302-89312 and SE54211-89216 is overgrown and means walking very close to a barbed wire fence. Path width needs increasing and b/wire protection	SE54302-89312 to SE54211-89216	619	3/7/21 have asked for a reply
27/10/2020	NYMNPAs			Deep heather and boggy area. No prow to be seen	NZ606-119 to NZ606-128	592	goes back many years
27/10/2020	NYMNPAs			Deep heather -no prow to be seen. Steps required at Percy Cross Rigg access point	NZ598-127 to NZ598-126	592	goes back many years
27/10/2020	NYMNPAs			Deep heather -no prow to be seen	NZ598-125 to NZ592-124	592	goes back many years
27/10/2020	NYMNPAs			Deep heather	NZ598-125 to NZ593-119	592	goes back many years
27/10/2020	NYMNPAs			Deep heather -no prow to be seen	NZ598-125 to NZ595-115	592	goes back many years
27/10/2020	NYMNPAs			Deep heather in places -no prow to be seen	SE563-949 to NZ551-954	592	goes back many years
27/10/2020	NYMNPAs			Deep heather in places -no prow to be seen	SE546-986 to SE538-977	592	goes back many years
27/10/2020	NYMNPAs			Deep heather in places -no prow to be seen	SE541-938 to SE546-936	592	goes back many years
27/10/2020	NYMNPAs			Deep heather in places -no prow to be seen	SE557-940 to SE565-939	592	goes back many years
07/11/2020	NYMNPAs	3999	22/04/2022	Stile need repairing and barbed wire stopping back	NZ54562-02312	581	3/7/21 Progress report requested
07/11/2020	NYMNPAs		09/11/2020	Stile need repairing and barbed wire stopping back	NZ55582-01973	581	3/7/21 Progress report requested
07/11/2020	NYMNPAs		09/11/2020	Stile need repairing and barbed wire stopping back	NZ56836-01933	581	3/7/21 Progress report requested
27/05/2021	NYMNPAs	3998	22/04/2022	Mud and barbed wire at gate	SE55521-99796	380	
27/05/2021	NYMNPAs	3997	22/04/2022	Stile step over too high	NZ54323-00626	380	
09/06/2021	NYMNPAs		11/06/2021	loose stones on the sloping stone slaps	NZ70271-06304, North End Farm	367	
24/06/2021	NYMNPAs		24/06/2021	Stile single step is very insecure	NZ65412-05447	352	
01/07/2021	NYMNPAs	3996	22/04/2022	Condition of UUR - R Hill email	NZ 787156 to 786148	345	
23/08/2021	NYMNPAs			Roadside signpost required - Peel Wood	NZ817-101	292	
25/08/2021	NYMNPAs	3835	22/04/2022	Signpost required	SE544-902	290	
06/09/2021	NYMNPAs	3836	22/04/2022	Request for a footpath across open access land, 1300 yds. Links two PROW	From NZ62135-12068 via NZ62117-11505 to NZ61655-11070	278	Alternative to link at Sleddale Farm which has been refused many times.
16/09/2021	NYMNPAs			Stile completely wrecked	NZ79271-05413	268	
16/09/2021	NYMNPAs			Stile needs needs urgent repairs	NZ79197-05414	268	
16/10/2021	NYMNPAs	3856	20/10/2021	Locked gate across path 428050	NZ473-003	238	
16/10/2021	NYMNPAs	3858	20/10/2021	Signage "Private land no public right of way"	NZ473-003	238	
21/10/2021	NYMNPAs			low iron bar across bridleway 428050	NZ473-003	233	
21/10/2021	NYMNPAs			No Signpost at minor road junction with path 428050	NZ473-003	233	
29/10/2021	NYMNPAs	3861	01/11/2021	Obstruction: impassable mud and stile missing, barbed wire adjacent	NZ509-003	225	Scugdale
07/11/2021	NYMNPAs	3901	01/01/2022	Steel mesh adjacent to stile	NZ534-003	216	Mill Lane, Ralsdale Mill
09/11/2021	NYMNPAs			Barbed wire alongside the path	Path number 516629	214	Newgate Bank (Rowmans ID 17319)
11/11/2021	NYMNPAs	3880	25/11/2021	Barbed wire around stile post	NZ703-125	212	off Gerrick Lane
17/11/2021	NYMNPAs	3881	25/11/2021	Stile tread to top rail too big	NZ585-050	206	
09/12/2021	NYMNPAs	3897	16/12/2021	Stile totally obstructed by hedge	SE485-865	184	Boltby
29/03/2022	NYMNPAs			Stile top step missing	NZ74624-08281	74	Houlsyke
13/04/2022	NYMNPAs	3994	21/04/2022	impossible route due to use by heavy vehicles	NZ617-137 to NZ616-129	59	JB - Sleddale